

Inspection Photos

Location Name: Silver King Pan Am Hayes #5-27

API: 05-103-07199



Silver King Pan Am Hayes #5-27 location photo. Pipe is covering an open casing.



Open casing with pipe removed.