


Inspection Photos
Location Name: J. Brophy 25-27
API Number: 125-07494



1. Lease sign on meter shed.



2. View of wellhead.

Inspection Photos
Location Name: J. Brophy 25-27
API Number: 125-07494



3. Produced water tank and signage.



4. Replaced produced water tank hatch.