

WELL CATEGORY : 3 - 6

WELL SITE INSPECTION FORM



LOCATION NWNW35-7N-67W FIELD New Windsor  
OPERATOR Martin COUNTY Weld  
WELL NAME Eaton Law #2 PERMIT # \_\_\_\_\_

DATE OF INSPECTION DURING DRILLING: \_\_\_\_\_

RIG \_\_\_\_\_ SURFACE CASING: \_\_\_\_\_ DEPTH: \_\_\_\_\_  
BOP'S \_\_\_\_\_ RETURNS: \_\_\_\_\_ WOC: \_\_\_\_\_  
CONTACT \_\_\_\_\_ CMT VOL: \_\_\_\_\_  
ADEQUATE AQUIFER PROTECTION? \_\_\_\_\_  
COMMENTS \_\_\_\_\_

DATE OF INSPECTION AFTER COMPLETION: \_\_\_\_\_

FRACED: YES \_\_\_\_\_ NO \_\_\_\_\_ PRODUCTION STRING: \_\_\_\_\_  
WATER DISPOSAL: PITS \_\_\_\_\_, INJECTED \_\_\_\_\_, COMMERCIAL \_\_\_\_\_, UNKNOWN \_\_\_\_\_, N.A. \_\_\_\_\_  
PITS: PERMIT Y \_\_\_\_\_ N \_\_\_\_\_, SKIM TANK Y \_\_\_\_\_ N \_\_\_\_\_, DIMENSIONS \_\_\_\_\_ GALLONS  
LEASE SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_ TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ FENCED: YES \_\_\_\_\_ NO \_\_\_\_\_  
SURFACE EQUIPMENT: \_\_\_\_\_  
COMMENTS: \_\_\_\_\_

DATE OF P&A INSPECTION \_\_\_\_\_

PITS BACKFILLED: YES \_\_\_\_\_ NO \_\_\_\_\_ SURFACE RECLAIMED: YES \_\_\_\_\_ NO \_\_\_\_\_  
HOLE MARKER: YES \_\_\_\_\_ NO \_\_\_\_\_ SITE CLEAN: YES \_\_\_\_\_ NO \_\_\_\_\_  
BOND RELEASE OK: YES \_\_\_\_\_ NO \_\_\_\_\_ LANDOWNER RELEASE: YES \_\_\_\_\_ NO \_\_\_\_\_  
COMMENTS: \_\_\_\_\_

DATE OF SAFETY INSPECTION 10/23/87

COMMENTS: #2 - producing, pit overflowing, running down lease road  
towards Brownell #1 (Sign for NWNW well says Eaton Law #1)  
\* Notified Gary Kruksdahl on 10/26/87 (987-1480)  
will draw down pit level  
INSPECTOR SP