


Inspection Photos  
Location Name: Monk 3-18  
API Number: 125-09821



1. Lease sign at battery.



2. Gas meter Calibration/Test Log inside meter.

Inspection Photos  
Location Name: Monk 3-18  
API Number: 125-09821



3. Lease sign at well location. Sign was down on ground at time of inspection.



4. Well location overview. Wellhead fencing was down at time of inspection.