

Inspection Photos

API: 071-06562

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/29/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the wellsite.



Inspection Photos



Photo 2. The fence around the pit is not maintained and needs to be removed or repaired.

