

Inspection Photos

API: 071-06559

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/29/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along the access road which remains per variance.



Inspection Photos



Photo 2. Facing west along the access road. The drainage crossing is stabilized with BMP's



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing west toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-06559 | Date: 4/29/2024

Inspection Photos



Photo 4. Facing west toward the location. The location is stabilized with perennial vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Facing northwest at the location fill slope. The location is stabilized with perennial vegetation.



Inspection Photos



Photo 6. West side of the location facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 7. Facing west at the beginning of the transect on location.



Photo 8. Facing east at the end of the transect on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 9. Facing southeast at the beginning of the transect off location.



Photo 10. Facing northwest at the end of the transect off location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

