

Interim Reclamation and Stormwater Inspection

Date: 5/2/24

Operator: PDC Energy Inc - 69175

Location ID: 447371

Inspection Document #: 713900585

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Johnson 17-1, Knutson K17-25

Location ID: 447371




Photo 1. The photo was taken at the tank battery location facing North. The photo illustrates the operator sign.

Photo 2. The photo was taken at the tank battery location facing Southeast. The photo illustrates gully erosion on the West side of the production pad.

Inspection Photos

Location Name: Johnson 17-1, Knutson K17-25

Location ID: 447371



Photo 3. The photo was taken at the tank battery location facing North. The photo illustrates the gully erosion and sedimentation off the location.

Photo 4. The photo was taken at the tank battery location facing North. The photo illustrates erosion on the East side of the production pad.

Note - Freshwater emergent wetlands extend to the boundary of the location disturbance.

Inspection Photos

Location Name: Johnson 17-1, Knutson K17-25

Location ID: 447371



Photo 5. The photo was taken at the tank battery location facing East. The photo illustrates the production pad boundary with interim areas.