

WELL CATEGORY : 3 - d

## WELL SITE INSPECTION FORM

LOCATION NWSW26-7N-67W  
OPERATOR Smith Marlin  
WELL NAME Brunner #1

FIELD New Windsor  
COUNTY Weld  
PERMIT # \_\_\_\_\_

## DATE OF INSPECTION DURING DRILLING: \_\_\_\_\_

RIG \_\_\_\_\_ SURFACE CASING: \_\_\_\_\_ DEPTH: \_\_\_\_\_  
BOP'S \_\_\_\_\_ RETURNS: \_\_\_\_\_ WOC: \_\_\_\_\_  
CONTACT \_\_\_\_\_ CMT VOL: \_\_\_\_\_  
ADEQUATE AQUIFER PROTECTION? \_\_\_\_\_  
COMMENTS \_\_\_\_\_

## DATE OF INSPECTION AFTER COMPLETION: \_\_\_\_\_

FRACED: YES \_\_\_ NO \_\_\_ PRODUCTION STRING: \_\_\_\_\_  
WATER DISPOSAL: PITS \_\_\_, INJECTED \_\_\_, COMMERCIAL \_\_\_, UNKNOWN \_\_\_, N.A. \_\_\_  
PITS: PERMIT Y \_\_\_ N \_\_\_, SKIM TANK Y \_\_\_ N \_\_\_, DIMENSIONS \_\_\_\_\_ GALLONS  
LEASE SIGN: YES \_\_\_ NO \_\_\_ TANK ID: YES \_\_\_ NO \_\_\_ NA \_\_\_ FENCED: YES \_\_\_ NO \_\_\_  
SURFACE EQUIPMENT: \_\_\_\_\_  
COMMENTS: \_\_\_\_\_

## DATE OF P&amp;A INSPECTION \_\_\_\_\_

PITS BACKFILLED: YES \_\_\_ NO \_\_\_ SURFACE RECLAIMED: YES \_\_\_ NO \_\_\_  
HOLE MARKER: YES \_\_\_ NO \_\_\_ SITE CLEAN: YES \_\_\_ NO \_\_\_  
BOND RELEASE OK: YES \_\_\_ NO \_\_\_ LANDOWNER RELEASE: YES \_\_\_ NO \_\_\_  
COMMENTS: \_\_\_\_\_

DATE OF SAFETY INSPECTION 10/23/87

COMMENTS: T.A. well, surface equip. removed, rods tied off.

INSPECTOR SP

API No. \_\_\_\_\_

P&A Inspected: Yes \_\_\_ No \_\_\_