

WELL CATEGORY : 3 - d

WELL SITE INSPECTION FORM



LOCATION NWSW26-7N-G7W
OPERATOR Marlin Oil
WELL NAME Brunner #1

FIELD Windsor
COUNTY Weld
PERMIT #

DATE OF INSPECTION DURING DRILLING:

RIG SURFACE CASING: DEPTH:
BOP'S RETURNS: WOC:
CONTACT CMT VOL:
ADEQUATE AQUIFER PROTECTION?
COMMENTS

DATE OF INSPECTION AFTER COMPLETION: 4/29/87

FRACED: YES NO PRODUCTION STRING:
WATER DISPOSAL: PITS , INJECTED , COMMERCIAL , UNKNOWN , N.A.
PITS: PERMIT Y N , SKIM TANK Y N ✓, DIMENSIONS GALLONS
LEASE SIGN: YES NO TANK ID: YES NO NA ✓ FENCED: YES NO
SURFACE EQUIPMENT:
COMMENTS: Rods tied off, no surface equipment at wellhead. T.A. well.

DATE OF P&A INSPECTION

PITS BACKFILLED: YES NO SURFACE RECLAIMED: YES NO
HOLE MARKER: YES NO SITE CLEAN: YES NO
BOND RELEASE OK: YES NO LANDOWNER RELEASE: YES NO
COMMENTS:

DATE OF SAFETY INSPECTION

COMMENTS:

INSPECTOR SP

API No.

P&A Inspected: Yes No