

Inspection Photos
Location Name: TREBOR-65N64W/12SWNE
Location #: 323714



Photo #1
Trebor B12-7 Wellsite
Temporarily Abandoned | TA
wellsite entrance
prior photo



Photo #2
Trebor B12-7 (123-13406) Wellsite
Temporarily Abandoned | TA
CA: Overgrown Vegetation
prior photo



Inspection Photos
Location Name: TREBOR-65N64W/12SWNE
Location #: 323714




Photo #3

Trebor B12-7 (123-13406) Wellsite

Temporarily Abandoned | TA

CA: Resolved. Overgrown Vegetation; Mitigated



Photo #4

Trebor B12-7 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Trebor B12-2, Trebor B12-6 ;

Plugged & Abandoned | PA

prior photo



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources