

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403723036

Date Received:

03/18/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10227  
Name of Operator: CHOLLA PETROLEUM INC

Address: 12404 PARK CENTRAL DR STE 380S

City: DALLAS State: TX Zip: 75251

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Tom Obenchain

214-455-4614

tao@chollapetro.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 679900584

Inspection Date: 10/23/2015

FIR Submit Date: 10/23/2015

FIR Status: SATISFACTORY

Inspected Operator Information:

Company Name: CHOLLA PETROLEUM INC

Company Number: 10227

Address: 6688 N CENTRAL EXPRESSWAY 1610

City: DALLAS State: TX Zip: 75206

LOCATION - Location ID: 314219

Location Name: LUKIE-DO-621S47W Number: 24SWNW County: PROWERS

Qtrqtr: SWN Sec: 24 Twp: 21S Range: 47W Meridian: 6  
W

Latitude: 38.212100 Longitude: -102.648450

FACILITY - API Number: 05-099-00 Facility ID: 285480

Facility Name: LUKIE-DO Number: 2-24

Qtrqtr: SWN Sec: 24 Twp: 21S Range: 47W Meridian: 6  
W

Latitude: 38.212100 Longitude: -102.648450

CORRECTIVE ACTIONS:

1 CA# 21096

Corrective Action: Install sign to comply with rule 210.

Date: 11/23/2015

Response: CA COMPLETED

Date of Completion: 11/06/2023

Operator  
Comment:

The well has been plugged and the location has been reclaimed.

ECMC Decision:

ECMC Representative:	
----------------------	--

Comment:

Title: Sr. Regulatory Analyst Date: 3/18/2024 1:31:11 PM

Total Attach: 1 Files