

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403223410

Date Received:
11/09/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

| Contact Name | Phone | Email |
|----------------|--------------|---------------------------------|
| Dacye Shull | 505-787-2027 | dshull@logosresourcesllc.com |
| Etta Trujillo | 505-324-4145 | etrujillo@logosresourcesllc.com |
| Vanessa Fields | 505-787-2218 | vfields@logosresourcesllc.com |

ECMC INSPECTION SUMMARY:

FIR Document Number: 702500650
Inspection Date: 10/20/2022 FIR Submit Date: 10/20/2022 FIR Status:

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC Company Number: 10679
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 325170

Location Name: BONDAD 33-9-N33N9W Number: 2NESE County: LA PLATA
Qtrqtr: NESE Sec: 2 Twp: 33N Range: 9W Meridian: N
Latitude: 37.130290 Longitude: -107.790060

FACILITY - API Number: 05-067-00 Facility ID: 214191

Facility Name: BONDAD 33-9 Number: 22
Qtrqtr: NESE Sec: 2 Twp: 33N Range: 9W Meridian: N
Latitude: 37.130290 Longitude: -107.790060

CORRECTIVE ACTIONS:

1 CA# 165555

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 11/04/2022

Response: CA COMPLETED

Date of Completion: 11/07/2022

Installed 1" plug on ball valve

Operator
Comment:

ECMC Decision:

ECMC
Representative:

2 CA# 165556

Corrective Action: Confirm Form 44 has been submitted or submit an eForm 44 Flowline Report per Rule 1101.a.

Date: 11/21/2022

Response: CA COMPLETED

Date of Completion: 11/09/2022

Operator
Comment:

To address safety and environmental issues, the valve connecting the domestic gas tap has been replaced to ensure it meets current regulations despite LOGOS having no ownership or operation of said valve. Currently, LOGOS has no access to the property and is therefore unable to access the landowner-owned flowline. LOGOS is currently contacting the landowner controlling and owning the lines leaving the gas tap. When a resolution with the landowner has been reached, the form 44 will be submitted as soon as reasonably practicable.

ECMC Decision:

ECMC
Representative:

3 CA# 165557

Corrective Action: Confirm Form 44 has been submitted or submit Form 44 per rule 1103.b.

Date: 11/20/2022

Response: CA COMPLETED

Date of Completion: 11/09/2022

Operator
Comment:

To address safety and environmental issues, the valve connecting the domestic gas tap has been replaced to ensure it meets current regulations despite LOGOS having no ownership or operation of said valve. Currently, LOGOS has no access to the property and is therefore unable to access the landowner-owned flowline. LOGOS is currently contacting the landowner controlling and owning the lines leaving the gas tap. When a resolution with the landowner has been reached, the form 44 will be submitted as soon as reasonably practicable.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

Installed 1" plug on ball valve
To address safety and environmental issues, the valve connecting the domestic gas tap has been replaced to ensure it meets current regulations despite LOGOS having no ownership or operation of said valve. Currently, LOGOS has no access to the property and is therefore unable to access the landowner-owned flowline. LOGOS is currently contacting the landowner controlling and owning the lines leaving the gas tap. When a resolution with the landowner has been reached, the form 44 will be submitted as soon as reasonably practicable.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dacye Shull

Signed: _____

Title: Regulatory Technician

Date: 11/9/2022 3:54:32 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

| | |
|-----------|--------------------------|
| 403223410 | FIR RESOLUTION SUBMITTED |
|-----------|--------------------------|

403223416

Installed 1" plug on ball valve

Total Attach: 2 Files