

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403650952

Date Received:

01/11/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Bongers, Brent

361-935-5633

bbongers@impetroresources.com

Axelson, John

john.axelson@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 688000066

Inspection Date: 09/19/2017

FIR Submit Date: 09/26/2017

FIR Status: _____

Inspected Operator Information:

Company Name: WARD & SON* ALFRED

Company Number: 94300

Address: P O BOX 737

City: OGALLALLA State: NE Zip: 69153

LOCATION - Location ID: 317261

Location Name: GETTMAN-61S55W Number: 14SESW County: _____

Qtrqr: SESW Sec: 14 Twp: 1S Range: 55W Meridian: 6

Latitude: 39.960206 Longitude: -103.509208

FACILITY - API Number: 05-121- -00 Facility ID: 101966

Facility Name: GETTMAN Number: _____

Qtrqr: SESW Sec: 14 Twp: 1S Range: 55W Meridian: 6

Latitude: 39.960206 Longitude: -103.509208

CORRECTIVE ACTIONS:

1 CA# 102976

Corrective Action: Provide soil sample analytical data, soil sample location drawing, soil disposal manifests on a supplemental eForm 27.

Date: 10/31/2017

Response: CA COMPLETED

Date of Completion: 01/05/2024

Operator Comment: The Gettman 14-14 well and associated tank battery were acquired by Impetro Resources, LLC (Operator #10690) in July 2023. Impetro has been unable to determine or identify detailed investigation and/or remediation activities that were performed by the previous operator, beyond the historical information submitted in the documents uploaded to the ECMC database. Impetro is in the production valuation process of the lease to determine whether it will be put back into production or decommissioned. Once a determination is made, Impetro

will provide a Form 27-S within 90-days from the submittal date of this report. If the location is put back into production, the remediation plan will include investigation activities regarding the former skim pit. Should Impetro determine to plug and reclaim the lease, the Form 27-S plan will include the skim pit investigation as well as standard plugging, and abandonment investigation procedures related to facility decommissioning. Form 27, Document #403646420, was filed 1/5/2024.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed: _____

Title: Compliance Specialist

Date: 1/11/2024 1:44:29 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403650952	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files