

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402476905

Date Received:

08/27/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 100321

Name of Operator: ROCKY MTN NATURAL GAS LLC ADBA BLACK HILLS ENERGY

Address: 1515 ARAPAHOE ST TOWER 1

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Woolley, Carmia

cwoolley@blm.gov

Mobley, Karla

kkmobley@fs.fed.us

Fischer, Alex

alex.fischer@state.co.us

Little, Ally

307-778-2123

Ally.Little@blackhillscorp.com

Warnes, Thomas

970-989-7053

Thomas.Warnes@blackhillscorp.com

Belcher, Austin

719-393-6639

Austin.Belcher@blackhillscorp.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 699700187

Inspection Date: 07/27/2020

FIR Submit Date: 08/12/2020

FIR Status: _____

Inspected Operator Information:

Company Name: ROCKY MTN NATURAL GAS LLC ADBA BLACK HILLS ENERGY

Company Number: 100321

Address: 1515 ARAPAHOE ST TOWER 1

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 314168

Location Name: Wolf Creek Unit Number: 9 County: _____

Qtrqr: NESW Sec: 36 Twp: 8S Range: 90W Meridian: 6

Latitude: 39.312831 Longitude: -107.395531

FACILITY - API Number: 05-097-00 Facility ID: 314168

Facility Name: Wolf Creek Unit Number: 9

Qtrqr: NESW Sec: 36 Twp: 8S Range: 90W Meridian: 6

Latitude: 39.312831 Longitude: -107.395531

CORRECTIVE ACTIONS:

1 CA# 141212

Corrective Action:

Date: 09/13/2020

Comply with Rule 603.f. and 907.A.

Operator shall provide documentation on how Black Hills will address the buried trash and debris on the location.

Response: CA COMPLETED

Date of Completion: 08/27/2020

Operator Comment: The trash and debris has been cleaned from the site. The felt liner is a geotextile fabric under the entire pad and will remain in place.

ECMC Decision: _____

ECMC Representative:

2 CA# 141213

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. and address the methanol and mercury impacted material per Rule 907.A.

Date: 09/12/2020

Response: CA COMPLETED

Date of Completion: 08/21/2020

Operator Comment: The remediation of methanol and mercury was completed and the final report was submitted via email on 8/21/2020. The final report has been attached to the report.

ECMC Decision: _____

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Austin Belcher

Signed: _____

Title: Environmental Professiona

Date: 8/27/2020 5:20:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402476905	FIR RESOLUTION SUBMITTED
402476913	Final Remediation Report

Total Attach: 2 Files