

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403738624

Date Received:

04/01/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 41550

Name of Operator: TYLER ROCKIES EXPLORATION LTD

Address: P O BOX 119

City: TYLER State: TX Zip: 75710-0119

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Strawn, Mark

texcomo@sbcglobal.net

ECMC INSPECTION SUMMARY:

FIR Document Number: 688304832

Inspection Date: 06/11/2019

FIR Submit Date: 06/12/2019

FIR Status: _____

Inspected Operator Information:

Company Name: TYLER ROCKIES EXPLORATION LTD

Company Number: 41550

Address: P O BOX 119

City: TYLER State: TX Zip: 75710-0119

LOCATION - Location ID: 320625

Location Name: PEORIA J-SAND UNIT-64S60W Number: 29SWSE County: ARAPAHOE

Qtrqr: SWSE Sec: 29 Twp: 4S Range: 60W Meridian: 6

Latitude: 39.669030 Longitude: -104.123280

FACILITY - API Number: 05-005-00 Facility ID: 204006

Facility Name: PEORIA J-SAND UNIT Number: 27

Qtrqr: SWSE Sec: 29 Twp: 4S Range: 60W Meridian: 6

Latitude: 39.669030 Longitude: -104.123280

CORRECTIVE ACTIONS:

1 CA# 126228

Corrective Action: The Peoria J-Sand Unit #27 is required to be either repaired and pass an MIT or plugged and abandoned by December 10, 2019 (six months).

Date: 12/10/2019

Response: CA COMPLETED

Date of Completion: 12/10/2019

Operator Comment: "Inspection 11/25/2019 Document # 688306380 states ""Well repair per Form 4402246858 started on 11/27/2019 by 300 PSI. There was 100 psi on bradenhead on 11/27/2019. Bradenhead was blown down to 0 psi. On 11/29/2019 300 PSI performed a pressure test with nitrogen from 0730 to 0930 to 335 psi and 4 psi on bradenhead that held. Not enough nitrogen to restart the MIT for COGCC inspector to witness so pumper filled hole with 300 gals and perform pretest MIT on 11/30/2019. Inspection 12/10/20219 Document # 688306478 states "Bradenhead, slight vac that died immediately, casing slight vac that died immediately, casing 0 psi.

Operator to submit Form 17." MIT passed and Form 17 was submitted.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Donahue

Signed: _____

Title: Compliance Specialist

Date: 4/1/2024 5:03:23 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403738624	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files