

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403582101

Date Received:
11/06/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10634
Name of Operator: P O & G OPERATING LLC
Address: 5847 SAN FELIPE SUITE 3200
City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Nash, Charlotte</u>	<u>(713) 589-8186</u>	<u>charlotte_nash@pogresources.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 701007515
Inspection Date: 10/16/2023 FIR Submit Date: 10/20/2023 FIR Status: _____

Inspected Operator Information:

Company Name: P O & G OPERATING LLC Company Number: 10634
Address: 5847 SAN FELIPE SUITE 3200
City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 321910

Location Name: SCHENK-613S44W Number: 5NWSW County: CHEYENNE
Qtrqtr: NWS Sec: 5 Twp: 13S Range: 44W Meridian: 6
W
Latitude: 38.947910 Longitude: -102.368800

FACILITY - API Number: 05-017-00 Facility ID: 208486

Facility Name: SCHENK Number: 1
Qtrqtr: NWS Sec: 5 Twp: 13S Range: 44W Meridian: 6
W
Latitude: 38.947910 Longitude: -102.368800

CORRECTIVE ACTIONS:

1 CA# 185614

Corrective Action: Remove equipment and begin final reclamation process Date: 11/06/2023

Response: CA COMPLETED Date of Completion: 11/02/2023

Operator Comment: All rods and tubing are removed from location. See pics of location.

ECMC Decision: _____

ECMC Representative:

2 CA# 185615

Corrective Action: Remove equipment and begin final reclamation process

Date: 11/06/2023

Response: CA COMPLETED

Date of Completion: 11/02/2023

Operator Comment: Pump Jack has been removed. See pics of location.

ECMC Decision:

ECMC Representative:

3 CA# 185616

Corrective Action: Remove equipment and begin final reclamation process

Date: 11/06/2023

Response: CA COMPLETED

Date of Completion: 11/04/2023

Operator Comment: Cathodic protection, electric panel and chemical drum has been removed 11/3/23. See pics of location.

ECMC Decision:

ECMC Representative:

4 CA# 185617

Corrective Action: Remove equipment and begin final reclamation process

Date: 11/06/2023

Response: CA COMPLETED

Date of Completion: 11/04/2023

Operator Comment: Electrical motor removed 11/3/23. See pics of location.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Waiting on soil sample testing to close around wellhead.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Charlotte Nash

Signed:

Title: Prod & Regulatory Analyst

Date: 11/6/2023 6:16:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403582101 FIR RESOLUTION SUBMITTED

Total Attach: 2 Files