

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/26NENE

Location ID: 335042



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/26NENE
Location ID: 335042
Date: 5/2/2024

Location ID: 335042

Date: 5/2/2024



Tank Battery – Photo #00917



Lack of Stabilization – Photo #00913

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/26NENE

Location ID: 335042

Date: 5/2/2024



Lack of Stabilization – Photo #00914



Lack of Stabilization – Photo #00915

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/26NENE

Location ID: 335042

Date: 5/2/2024



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #00916