

Inspection Photos
Location Name: Lueking 42-19X 5N46W
API Number: 125-10822



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Lueking 42-19X 5N46W
API Number: 125-10822



3. Deadman & marker 1.



4. Deadman & marker 2.

Inspection Photos
Location Name: Lueking 42-19X 5N46W
API Number: 125-10822



5. Deadman & marker 3.



6. Deadman & marker 4.