

Inspection Photos

May 2nd, 2024

Operator: Maralex Resources Inc - 53255

Location ID: 333661

Inspection Document #: 714000740

La Plata County, CO

Township: NWNW 11 33N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Keegan Patrick 33-7-11 1, 3B
Location ID: 333661



5/2/24
+37.118736,-107.578072
216° SW



5/2/24
+37.122741,-107.582690
281° W

Maralex Resources, Inc.
970-563-4000
Emergency Services - 911
KEEGAN PATRICK 33-7-11 #1
API# 05-067-08915
Access from County Road 336
La Plata County
NNW Sec 11 T33N R7W
Lat: 37.12258 Long: -107.58267



5/2/24
+37.122937,-107.582639
267° W

Maralex Resources, Inc.
970-563-4000
Emergency Services - 911
KEEGAN PATRICK 33-7-11 #3B
API# 05-067-09478
Access from County Road 336
La Plata County
NNW Sec 11 T33N R7W
Lat: 37.12282 Long: -107.58265

Photo 1. View of the well disturbance taken from the entrance facing center.

Inspection Photos

Location Name: Keegan Patrick 33-7-11 1, 3B

Location ID: 333661



Photo 2. Impacted surface material observed at the 3B well head.

Inspection Photos

Location Name: Keegan Patrick 33-7-11 1, 3B

Location ID: 333661



Photo 3. View of wildlife netting at lube oil tank secondary containment that is no longer functioning.

Inspection Photos

Location Name: Keegan Patrick 33-7-11 1, 3B

Location ID: 333661



Photo 4. View of unused oil and gas equipment stored on location.

Inspection Photos

Location Name: Keegan Patrick 33-7-11 1, 3B

Location ID: 333661



5/2/24
+37.122357,-107.582557
7° N

Photo 5. View of the eastern interim reclamation area facing north. Vegetation is minimal as area is surrounded by an active cow pasture.