

# Inspection Photos

May 2nd, 2024

Operator: Maralex Resources Inc - 53255

Location ID: 325560

Inspection Document #: 714000741

La Plata County, CO

Township: NWNE 10 33N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Heikkinen 1-19  
Location ID: 325560

5/2/24  
+37.122615,-107.592881  
102° E



**Photo 1.** View of the well disturbance taken from the entrance facing center.





Inspection Photos  
Location Name: Heikkinen 1-19  
Location ID: 325560

5/2/24  
+37.122555,-107.592715  
174° S



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** Produced water tank sign/placard corrective action identified in the previous inspection doc #702500687 has been addressed/resolved.

API #: 067-06609



Inspection Photos  
Location Name: Heikkinen 1-19  
Location ID: 325560



**Photo 3.** Weedy debris at produced water tank berm have not been removed.  
Maintenance on secondary containment is required.



Inspection Photos  
Location Name: Heikkinen 1-19  
Location ID: 325560





Inspection Photos  
Location Name: Heikkinen 1-19  
Location ID: 325560

5/2/24  
+37.122758,-107.592145  
15° N



Photo 5. Capacity not listed at tank battery produced water tanks.