

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: North Platte T-27 Pad

Loc ID: 441915

Inspection: 708200986



Exhibit A



Exhibit B



Exhibit C

CA: This location does not comply with Rule 1003. During this inspection, it was observed that interim areas are not progressing towards Rule 1003 standards and regulations with evidence of undesirable vegetation (Russian thistle and kochia) and areas of non-uniform vegetation cover resulting in exposed soils. Additional reclamation activities are required in order to comply with Rule 1003. Refer to attached inspection photos. Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil and continue to monitor and manage this site until the location meets Rule 1003 standards.

CA Resolution: Operator has reported that the location has been mowed, re-seeded, and crimped with straw mulch to encourage desired vegetation growth and to comply with Rule 1003.