

Inspection Photos

API: 071-08693

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/6/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the wellsite.



Inspection Photos



Photo 2. There is still a dripping leak coming from the wellhead that needs to be repaired..

