

# Inspection Photos

API: 071-07610

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 5/6/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 2.** Facing west toward the fill slope which is stabilized with perennial vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources