

Inspection Photos

API: 071-07547

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/6/2024

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing north along the access road.



Inspection Photos



Photo 2. Facing north toward the wellsite.

