

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Patterson/SG 24-27

Location ID: 424971

Date: 5/7/2024



May 7, 2024 at 12:56:39
Parachute CO 81635
United States



May 7, 2024 at 12:59:03
Parachute CO 81635
United States

Location Entrance – Photo #00965

Wellheads – Photo #00970

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Patterson/SG 24-27

Location ID: 424971

Date: 5/7/2024



May 7, 2024 at 12:58:25
Parachute CO 81635
United States

Separators – Photo #00968



May 7, 2024 at 12:57:30
Parachute CO 81635
United States

Tank Battery – Photo #00966

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Patterson/SG 24-27

Location ID: 424971

Date: 5/7/2024



Lack of Stabilization – Photo #00969



Lack of Stabilization – Photo #00971

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Patterson/SG 24-27

Location ID: 424971

Date: 5/7/2024



May 7, 2024 at 13:01:02
Parachute CO 81635
United States



May 7, 2024 at 13:01:13
Parachute CO 81635
United States

Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #00972

Insufficient Administrative Stormwater BMP – Photo #00973