

WELL SITE INSPECTION FORM

WELL NAME CANAL #1API NUMBER 05 -OPERATOR H&R

PERMIT NUMBER _____

LOCATION SENE34-7N-67WCOUNTY WELDFIELD WINDSORINSPECTOR R. VanSickle

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) _____ FAIL(N) _____ DATE _____ FN _____ FD _____ WO _____

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____

CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____

RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____

DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____

TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____

SKIM PIT: _____ gal TANKS: () _____ bbls

EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____

METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____

HOLE PLUGGED: YES _____ NO _____ PITS BACKFILLED: YES _____ NO _____

MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____

BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION 2-28-90COMMENTS 2-400 BBL BOLTED TANKS, TREATER, SEVERAL PITSW/SLUDGE ON BTM. H2O COMING INTO COFFIN & THEN INTO PITS