

Inspection Photos

05/06/2024

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 485124

Inspection Doc: 696205807

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 485124



Photo 1: Photo taken from the planned Location entrance, facing south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 485124



Photo 2: Photo taken from the access road. Photo example of a potential culvert Location under review.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 485124



Photo 3: Access road photos.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources