

WELL NAME: GOLDEN EAGLE 34-03, API #: 071-06182, INSP. # 695109520



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION



PHOTO 3: WELLHEAD AND EQUIPMENT



WGS84 $\pm 17\text{ft}$ 37.13488, -104.87866 Δ ft $\pm 10\text{ft}$ 7133 \circ, M ± 14 S193



PHOTO 4: WELL EQUIPMENT





PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 6-8-2024.



PHOTO 6: AREA OF IMPACTED SOIL NEAR PUMPJACK SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 6-8-2024.






PHOTO 7: NO CURRENT CALIBRATION LOG POSTED AT METER. PROVIDE AREA FIELD INSPECTOR (@ tombeardslee@state.co.us) A COPY OF THE GAS METER CALIBRATION RECORD OR KEEP A COPY OF LAST CALIBRATION RECORD ON LOCATION. CA DATE 6-8-2024.



PHOTO 8: OILY WASTE IN ENGINE SKID. COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 5-9-2024.