

# Final Reclamation and Stormwater Inspection

Date: 04/26/2024

Operator: PDC ENERGY INC - 69175

Location ID: 445423

Inspection Document #: 708201217

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Photo 1.** Taken near the northeast side of the former tank battery location. It appears that final reclamation activities have been performed- equipment has been removed and germination was observed throughout. The location will be inspected at a later date to verify vegetative compliance.



Inspection Photos  
Location Name: Yaklich 5-11  
Location ID: 445423



**Photo 2.** Taken near the southeast side of the former tank battery location; see comments in Photo 1.



Inspection Photos  
Location Name: Yaklich 5-11  
Location ID: 445423



**Photo 3.** Taken near the northwest side of the former tank battery location; see comments in Photo 1.



Inspection Photos  
Location Name: Yaklich 5-11  
Location ID: 445423



**Photo 4.** Taken near the southwest side of the former well location. Trash and debris was observed throughout the western portion of the location.