

Final Reclamation and Stormwater Inspection

Date: 04/26/2024

Operator: PDC ENERGY INC - 69175

Location ID: 447210

Inspection Document #: 708201219

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Yaklich PM F 11-03, 6
Location ID: 447210



Photo 1. Facing southwest at the former tank battery location. It appears that reclamation activities have been performed and the location is progressing towards Rule 1004 standards and regulations. Access road (red arrow) has not been reclaimed per the 1004 Rules.

Inspection Photos
Location Name: Yaklich PM F 11-03, 6
Location ID: 447210



Photo 2. Facing northwest at the former tank battery location; see comments in Photo 1.

Inspection Photos

Location Name: Yaklich PM F 11-03, 6

Location ID: 447210



Photo 3. Facing northeast at the former tank battery location; see comments in Photo 1.

Inspection Photos
Location Name: Yaklich PM F 11-03, 6
Location ID: 447210



Photo 4. Facing southeast at the former tank battery location; see comments in Photo 1.

Inspection Photos
Location Name: Yaklich PM F 11-03, 6
Location ID: 447210



Photo 5. Historical imagery from 07/05/1978 illustrates that portions of the access road (outlined in red) did not exist prior to oil and gas development. Red arrow indicates a reference point (house) for Photo 5 and Photo 6.

Inspection Photos
Location Name: Yaklich PM F 11-03, 6
Location ID: 447210



Photo 6. Google Earth aerial imagery taken circa 05/2023 illustrating the highlighted portion of the access road that did not exist prior to oil and gas development.