

Inspection Photos

Location Name: LARAMIE ENERGY LLC, CC/0629-02 Pad

Location ID: 335149

Date: 5/8/2024



Wellheads/PA Well – Photo #01003



Separators – Photo #01005

Inspection Photos

Location Name: LARAMIE ENERGY LLC, CC/0629-02 Pad

Location ID: 335149

Date: 5/8/2024



Tank Battery – Photo #01006



PA Well – Photo #01004

Inspection Photos

Location Name: LARAMIE ENERGY LLC, CC/0629-02 Pad

Location ID: 335149

Date: 5/8/2024



Lack of Stabilization – Photo #01008



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #01009**