

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6362 From entrance to location



Photo # 6363 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6364 Location



Photo # 6365 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6366 Location



Photo # 6367 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6368 Location



Photo # 6369 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6370 Location



Photo # 6371 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6372 Location



Photo # 6373 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6374 Location

Photo # 6375 Unused equipment

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6376 Inaccurate info on tank labeling/does not comply with CECMC rules

Photo # 6377

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6378 Inaccurate info on tank labeling/does not comply with CECMC rules

Photo # 6379 Flowline heating insulation open ended /wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6380 Tank battery lacks required signage



Photo # 6381 Tank battery lacks required signage

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6382 Tank battery lacks required signage



Photo # 6383 Tank battery lacks required signage

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6384 Debris



Photo # 6385 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL PF-31 Pad

Location #: 334085



Photo # 6386 Stained gravel in secondary containment