

# Inspection Photos

API: 011-05057

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 5/8/2024

County: Prowers



## Inspection Photos



**Photo 1.** Drone photo facing down toward the wellsite. There is an area with no vegetation which appears impacted soil from a historical spill.



## Inspection Photos



**Photo 2.** Facing northeast toward the wellsite.



## Inspection Photos



**Photo 2.** There is concrete debris and unused pipe that needs to be removed..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 011-05057 | Date: 5/8/2024

## Inspection Photos



**Photo 3.** Northeast corner of the location. There is part of a metal shed and unused pipe that needs to be removed.

