

# Interim Reclamation and Stormwater Inspection

Date: 04/26/2024

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 440776

Inspection Document #: 708201213

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 1.** Unused equipment must be removed or returned to service.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 2.** Former compressor location; unused equipment identified in the red polygon must be returned to service or removed from the location.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 3.** Unused equipment continued from Photo 2.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 4.** Unused equipment continued from Photo 2 and stained soil, indicated by red arrow.



**Photo 5.** Unmarked riser/unused equipment, south of compressor station.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 6.** Unused equipment south of compressor station must be returned to service or removed from the location.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photos 7 & 8.** Example of trash/debris observed on the south end of the location. Operator shall self inspected the entire location and remove any trash/debris.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 9.** Unused equipment must be returned to service or removed from the location.



**Photo 10.** Stained soil at compressor station.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 11.** Equipment labels are faded, peeling, cracked.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 12.** Debris/trash observed within equipment.



**Photo 13.** Tank labels/NFPA placards are faded, peeling, cracked.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 14.** Tank labels/NFPA placards are faded, peeling, cracked.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 15.** Tank labels/NFPA placards are faded, peeling, cracked.



**Photo 16.** Oily rag observed within tank battery secondary containment.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



Photo 17. Sign at tank battery is peeling, faded, cracked.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photos 18 & 19.** Colorado List C Noxious weed (field bindweed) observed on the northwest corner of the tank battery location.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 20.** Northern interim areas have evidence of undesirable vegetation (kochia) growing throughout. Refer to FIR (doc #708201214) for eastern interim areas associated with Location 440761. Note - red arrow is only an example as kochia was observed throughout.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 21.** Western interim areas have evidence of undesirable vegetation (kochia) growing throughout. Refer to FIR (doc #708201214) for eastern interim areas associated with Location 440761. Note - red arrow is only an example as kochia was observed throughout.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 22.** Western interim areas have evidence of undesirable vegetation (kochia) growing throughout. Refer to FIR (doc #708201214) for eastern interim areas associated with Location 440761. Note - red arrow is only an example as kochia was observed throughout.

Inspection Photos  
Location Name: Arellano 10-L Facility  
Location ID: 440776



**Photo 23.** Northern interim areas have evidence of undesirable vegetation (kochia) growing throughout. Refer to FIR (doc #708201214) for eastern interim areas associated with Location 440761. Note - red arrow is only an example as kochia was observed throughout.