

## State of Colorado

## Energy &amp; Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403731343

Date Received:

05/10/2024

Spill report taken by:

Robinson, Taylor

Spill/Release Point ID:

484556

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

## OPERATOR INFORMATION

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Operator No: 47120	<b>Phone Numbers</b>
Address: P O BOX 173779		Phone: (713) 350-4906
City: DENVER	State: CO	Zip: 80217-3779
Contact Person: Ariana Ochoa		Mobile: ( )
		Email: DJRemediation_Forms@oxy.com

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

## INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403396708

Initial Report Date: 05/08/2023 Date of Discovery: 05/05/2023 Spill Type: Recent Spill

## Spill/Release Point Location:

QTRQTR NESW SEC 33 TWP 3N RNG 68W MERIDIAN 6

Latitude: 40.181861 Longitude: -105.008082

Municipality (if within municipal boundaries): County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

☐ Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

## Reference Location:

Facility Type: TANK BATTERY

☒ Facility/Location ID No 449884

Spill/Release Point Name: Newby 30N-4 Facility

☐ Well API No. (Only if the reference facility is well) 05- -☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): Unknown

Estimated Condensate Spill Volume(bbl): Unknown

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&amp;P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: Sunny 69°F

Surface Owner: FEE Other(Specify):

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A release of 6.2 barrels occurred within secondary containment at the Newby 30N-4 Facility. This release has been controlled and is not an active release. Assessment activities are ongoing. The assessment details and a photo log will be included in a supplemental report. The topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

### OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
5/5/2023	Surface Owner	Surface Owner	---	Notified via voicemail
5/5/2023	Weld County	Weld County	---	Notified via email

### REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

- No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.
- Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_
- Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_
- Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_
- Yes Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.
- No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.
- No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak
- Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)
- Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_
- Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_
- Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_
- Was there damage during excavation? \_\_\_\_\_
- Was CO 811 notified prior to excavation? \_\_\_\_\_
- No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.
- Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_
- No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:
- ☐ The presence of free product or hydrocarbon sheen Surface Water
- ☐ The presence of free product or hydrocarbon sheen on Groundwater
- ☐ The presence of contaminated soil in contact with Groundwater
- ☐ The presence of contaminated soil in contact with Surface water

No	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

## SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 05/10/2024		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	2	2	<input type="checkbox"/>
CONDENSATE	2	2	<input type="checkbox"/>
PRODUCED WATER	2	2	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>YES</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, <b>including walls &amp; floor regardless of construction material</b>, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>40</u>		Width of Impact (feet): <u>34</u>	
Depth of Impact (feet BGS): <u>6</u>		Depth of Impact (inches BGS): _____	
How was extent determined?			
Between May 5 and July 24, 2023, assessment activities were conducted to delineate remaining soil impacts at the release location. Confirmation soil samples were collected from the excavation at depths of 2 feet below ground surface (ft bgs), 4 ft bgs, and 6 ft bgs. Laboratory analytical results indicated all constituent concentrations were within the ECMC Table 915-1 allowable levels or within the analytical variability at all sample locations, with the exception of barium at the SS06@2' and SS07@6' locations and selenium at the SS06@4', SS07@2',4', and SS08@2',4' locations. However, the production facility infrastructure will be replaced and/or remain in place at this time, and the surface area will maintain its current usage. As the remaining elevated analytes are inorganic in nature, this material will be left in place pending future facility decommissioning. The PID readings and soil sample results are summarized in Table 1 and Table 2, respectively, and the laboratory reports are attached.			
Soil/Geology Description:			
Silty Sand (SM)			
Depth to Groundwater (feet BGS) <u>20</u>		Number Water Wells within 1/2 mile radius: <u>8</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>850</u> None <input type="checkbox"/>	Surface Water <u>970</u> None <input type="checkbox"/>	
	Wetlands <u>690</u> None <input type="checkbox"/>	Springs _____    None <input checked="" type="checkbox"/>	
	Livestock <u>2430</u> None <input type="checkbox"/>	Occupied Building <u>2500</u> None <input type="checkbox"/>	
Additional Spill Details Not Provided Above:			
Approximately 68 cubic yards of impacted soil were removed from the site and transported to the Aggregate Recycle Facility for recycling. Disposal records are kept on file and are available upon request.			

## CORRECTIVE ACTIONS

#1	Supplemental Report Date:	05/10/2024
Root Cause of Spill/Release		
Equipment Failure		
Other (specify)		
Type of Equipment at Point of Spill/Release:		
Horizontal Separator		
If "Other" selected above, specify or describe here:		
Describe Incident & Root Cause (include specific equipment and point of failure)		
A release of approximately 6.2 barrels occurred when internal corrosion caused a hole on the produced water line, located in the separator cabinet, at the Newby 30N-34HZ Facility. This release has been controlled and is no longer active.		
Describe measures taken to prevent the problem(s) from reoccurring:		
The release has been controlled and the equipment has been repaired. Additionally, corrosion inhibitors are being used to help decrease and manage internal corrosion.		
Volume of Soil Excavated (cubic yards):		
68		
Disposition of Excavated Soil (attach documentation)		
<input type="checkbox"/> Offsite Disposal		
<input type="checkbox"/> Onsite Treatment		
<input checked="" type="checkbox"/> Other (specify)		
Aggregate Recycle Facility		
Volume of Impacted Ground Water Removed (bbls):		
0		
Volume of Impacted Surface Water Removed (bbls):		
0		

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

- Basis for Closure:
- ☒ Corrective Actions Completed (documentation attached, check all that apply)
    - ☐ Horizontal and Vertical extents of impacts have been delineated.
    - ☐ Documentation of compliance with Table 915-1 is attached.
    - ☒ All E&P Waste has been properly treated or disposed.
    - ☐ Work proceeding under an approved Form 27 (Rule 912.c).  
Form 27 Remediation Project No:
    - ☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

## OPERATOR COMMENTS:

Per the COA for the Form 19 NFA Status Request dated August 11, 2023 (Document No. 403490666), Kerr-McGee has omitted the two background soil sample locations (Native-BG03 and Native-BG04) from the calculations, as requested. Based on the analytical and soil screening data provided herein, assessment is complete at this time and Kerr-McGee is requesting an NFA determination for this location.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Ariana Ochoa

Title: Sr. HSE Advisor Date: 05/10/2024 Email: DJRemediation\_Forms@oxy.com

COA Type	Description
0 COA	

### ATTACHMENT LIST

Att Doc Num

Name

403731374	ANALYTICAL RESULTS
403731375	PHOTO DOCUMENTATION
403731377	SOIL SAMPLE LOCATION MAP

Total Attach: 3 Files

### General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)