

Inspection Photos
Location Name: Nugent LD06-665
Location ID: 440366



Photo 1 – Gas Lift Injection Meter Houses



Photo 2 – Wellheads

Inspection Photos
Location Name: Nugent LD06-665
Location ID: 440366




Photo 3 – Nugent LD06-655 Wellhead



Photo 4 – Nugent LD06-665 Wellhead