

Inspection Photos  
Location Name: Lone Unit B Lease Battery  
Location ID: 311302



Photo 1 Location.



Photo 2 TB sign.

**Inspection Photos**  
**Location Name: Lone Unit B Lease Battery**  
**Location ID: 311302**



**Photo 3 Tank Battery.**



**Photo 4 Flow line manifold.**



**Inspection Photos**  
**Location Name: Lone Unit B Lease Battery**  
**Location ID: 311302**



**Photo 5 Gas Meter Run.**



**Photo 6 Horizontal heater treater.**

**Inspection Photos**  
**Location Name: Ione Unit B Lease Battery**  
**Location ID: 311302**



**Photo 7 HHT gasket slowly leaking.**



**Photo 8 HHT leak dripping onto the ground.**



**Inspection Photos**  
**Location Name: Lone Unit B Lease Battery**  
**Location ID: 311302**



**Photo 9 Stained soil to the west of the Horizontal Heater Treater.**



**Photo 10 Stained soil to the west of the Horizontal Heater Treater.**



**Inspection Photos**  
**Location Name: Lone Unit B Lease Battery**  
**Location ID: 311302**



**Photo 11 Stained soil around flow line riser west of the TB.**



**Photo 12 Stained soil around flow line riser west of the TB.**



**Inspection Photos**  
**Location Name: Lone Unit B Lease Battery**  
**Location ID: 311302**



**Photo 13 Stained soil around flow line riser west of the TB.**



**Photo 14 Flow line riser.**