

Inspection Photos
Location Name: Elton N. Miller E 1
Location ID: 318528



Photo 1 Location.



Photo 2 WH/sign.

Inspection Photos
Location Name: Elton N. Miller E 1
Location ID: 318528



Photo 3 WH sign is faded, peeling.



Photo 4 Unnecessary equipment, old pump jack base.

Inspection Photos
Location Name: Elton N. Miller E 1
Location ID: 318528



Photo 5 Unnecessary equipment Ancillary equipment fence enclosed in plywood.



Photo 6 Unnecessary equipment Ancillary equipment fence enclosed in plywood.