



Photo 1. Location signage removed.



Photo 2. Concrete debris on location, next to pothole from flowline removed.



Photo 3. Plastic piping (debris) observed on the northern end of the location, removed.

Photo 4. Taken along the access road, facing northwest. The reclaimed access road



Photo 5. Taken along the access road, facing south.



Photo 6. Facing SE on NW end of pad



BERNHARDT ST PC N 36-17 and BERNHARDT ST PC N36-27 COA pics

Photo 7. On NE side of pad facing SW



BERNHARDT ST PC N 36-17 and BERNHARDT ST PC N36-27 COA pics

Photo 8. On SE side of pad facing NW



Photo 9. On SW side of pad facing NE

