

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403788147

Date Received:

05/13/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000705

Inspection Date: 04/23/2024

FIR Submit Date: 04/24/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 320859

Location Name: SEIBEL GAS UNIT B-N32N5W Number: 17SENE County: _____

Qtrqtr: SENE Sec: 17 Twp: 32N Range: 5W Meridian: N

Latitude: 37.020232 Longitude: -107.409024

FACILITY - API Number: 05-007- -00 Facility ID: 320859

Facility Name: SEIBEL GAS UNIT B-N32N5W Number: 17SENE

Qtrqtr: SENE Sec: 17 Twp: 32N Range: 5W Meridian: N

Latitude: 37.020232 Longitude: -107.409024

CORRECTIVE ACTIONS:

1 CA# 194676

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.

Date: 04/29/2024

Response: CA COMPLETED

Date of Completion: 05/01/2024

Operator Comment: Stained soil removed and equipment repaired.

ECMC Decision: _____

--

Date: 5/13/2024 11:14:52 AM

Total Attach: 1 Files