

Seibel B1


Date completed 5/8/2024

document #714000705

Stained soil at wellhead removed.

Weeds removed.

Erosion area repaired.



Date completed 5/1/24.
Stain cleaned up and removed.

