

Inspection Photos

Location: Baughman # 7

Facility ID: 324836

[Related](#)
[Insp](#)
[MIT](#)
[GIS](#)
[Doc](#)
[COA](#)

[Wellbore](#)
[Orders](#)
[Bradenhead](#)

Surface Location		Well Classification: OW	Status: PR - 11/1/2022
API# 05-061-06392		Click Here for Transporter Gatherer Info	
Well Name/No: BAUGHMAN #7			
<small>(Click Well Name for Production Data)</small>			
Operator: CHEMCO INC - 16520		Federal Or State Lease #:	
<small>(Click Operator Name for Company Detail Report)</small>			
Facility Status:	PR	Status Date	11/1/2022
FacilityID:	213031	LocationID:	324836
County:	KIOWA #061	Location:	SWSW 2 19S45W 6
Field:	CAVALRY - #10340	Elevation:	3922 ft.
Planned Location: 660FSL 660 FWL		Lat/Long: 38.427912 / -102.434224 Calculated From	

Primary

Rep

Out Of S

O

Inac

Nc

De

Lc

BOE/M

Prod

Februar



Photo 1 –Scout Card, no well placard onsite

Photo 2 – Pump Jack

Inspection Photos
Location: Baughman # 7
Facility ID: 324836



Photo 3 – Oil stained soils

Photo 4 – Oil stained soils

Inspection Photos
Location: Baughman # 7
Facility ID: 324836



Photo 5 – Oil stained soils

Photo 6 – 55 gallon drums on site, one in containment

Inspection Photos
Location: Baughman # 7
Facility ID: 324836



Photo 7 – Well scale near wellhead

Photo 8 – Tank Battery

Inspection Photos
Location: Baughman # 7
Facility ID: 324836



Photo 9 – Tanks and piping

**Photo 10 – 55 Gallon drum blown off
location, east of well pad**