

Inspection Photos  
Location: Baughman # 8  
Facility ID: 324848

< > AA ecmc.state.co.us

<b>Surface Location</b>		<b>Well Classification: OW</b>	<b>St 1:</b>
API# <b>05-061-06488</b>			
<u>Well Name/No:</u> <a href="#">BAUGHMAN #8</a>		<a href="#">Click Here for Transporter Gatherer Info</a>	
(Click Well Name for Production Data)			
<u>Operator:</u> <a href="#">CHEMCO INC - 16520</a>		Federal Or State Lease #:	
(Click Operator Name for Company Detail Report)			
Facility Status:	SI	Status Date	12/
FacilityID:	<b>213127</b>	LocationID:	324
County:	KIOWA #061	Location:	SES 6
Field:	CAVALRY - #10340	Elevation:	393




Photo 1 –Scout Card, no well placard on site

Photo 2 – Pump Jack

**Inspection Photos**  
**Location: Baughman # 8**  
**Facility ID: 324848**



**Photo 3 – Pump Jack**




**Photo 4 – Impacted soils around wellhead**



**Inspection Photos**  
**Location: Baughman # 8**  
**Facility ID: 324848**



**Photo 5 – Oil Stained soils**



**Photo 6 – Impacted soils adjacent to wellhead**



**Inspection Photos**  
**Location: Baughman # 8**  
**Facility ID: 324848**



**Photo 7 – Heater Treater base.**



**Photo 8 – Impacted soils i**



**Inspection Photos**  
**Location: Baughman # 8**  
**Facility ID: 324848**



**Photo 9 – Breach in Secondary Containment**



**Photo 10 – Impacted soils in Secondary Containment**