

Inspection Photos
Location: King Pyles # 4 Tank Battery
Facility ID: 470688



**Photo 1 –Location Placard at Tank Battery,
Remediation # 21723**

**Photo 2 – Open Remediation excavation Impacted
soils observed under tank**

Inspection Photos
Location: King Pyles # 4 Tank Battery
Facility ID: 470688



Photo 3 – Tanks Battery looking north

Photo 4 – Unused tanks looking north

Inspection Photos
Location: King Pyles # 4 Tank Battery
Facility ID: 470688



Photo 5 – unused tanks looking west

Photo 6 – Unused Tanks looking south

Inspection Photos
Location: King Pyles # 4 Tank Battery
Facility ID: 470688



Photo 7 – Tanks looking south, area of impacted soils at arrow.

Photo 8 – Heater Treater

Inspection Photos
Location: King Pyles # 4 Tank Battery
Facility ID: 470688



Photo 9 – Heater Treater