

Inspection Photos  
Location: Pyles, Bertha # 2  
Facility ID: 324792



Photo 1 –Well Placard onsite

Photo 2 – Tank onsite without labeling

Inspection Photos  
Location: Pyles, Bertha # 2  
Facility ID: 324792



Photo 3 – Spoil Pile



Photo 4 – Unused Tank on location. No plumbing to tank

Inspection Photos  
Location: Pyles, Bertha # 2  
Facility ID: 324792



Photo 5 – Treater



Photo 6 – Tank Battery, Open Excavation for Remediation # 34392

**Inspection Photos**  
**Location: Pyles, Bertha # 2**  
**Facility ID: 324792**



**Photo 7 – Open Excavation for Remediation # 34392**

**Photo 8 – Tank Battery**

**Inspection Photos**  
**Location: Pyles, Bertha # 2**  
**Facility ID: 324792**



**Photo 9 – Tank Battery**



**Photo 10 – Tank Battery**