

Inspection Photos  
Location: Foster # 1  
Facility ID: 324795



Photo 1 –Well Placard



Photo 2 – Pump Jack, location of historical wellhead



**Inspection Photos**  
**Location: Foster # 1**  
**Facility ID: 324795**



**Photo 3 – Wellhead excavation**



**Photo 4 – Soils pile**



**Inspection Photos**  
**Location: Foster # 1**  
**Facility ID: 324795**



**Photo 5 – Tank Battery / Treater location**



**Photo 6 – Tank Battery / Treater location**



**Inspection Photos**  
**Location: Foster # 1**  
**Facility ID: 324795**



**Photo 7 – Wellhead.**



**Photo 8 – Unused equipment**





**Inspection Photos**  
**Location: Foster # 1**  
**Facility ID: 324795**



**Photo 9 – Historical Impacts to soils Northwest of location**



**Photo 10 – Historical Impacts to soils Northwest of location**

**Inspection Photos**  
**Location: Foster # 1**  
**Facility ID: 324795**



**Photo 11 Historical Impacts to soils Northwest of location**



**Photo 12 – Historical Impacts to soils Northwest of location**