

Inspection Photos
Location Name: PHERSON-65N64W/2NESW
Location #: 323041



Photo #1

Pherson 2-2 (123-12473) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 120 yds.



Photo #2

Pherson 2-2, Buckmur B 2-14, B 2-25 Battery site
Abandoned: ALL Equipment Removed
Plugged & Abandoned | PA
3: wells

