

Inspection Photos

Location Name: TEP Rocky Mountain LLC Juhan Booster Station

Location # 323868

Facility # 479766



Photo # 6714 From entrance to location




Photo # 6715 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC Juhan Booster Station

Location # 323868

Facility # 479766



Photo # 6716 Location



Photo # 6717 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC Juhan Booster Station

Location # 323868

Facility # 479766



May 13, 2024 at 12:48:36 PM



May 13, 2024 at 12:47:53 PM

Photo # 6718 Location

Photo # 6719 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC Juhan Booster Station

Location # 323868

Facility # 479766



Photo # 6720 Location



Photo # 6721 Tank label weathered & starting to become illegible.

Inspection Photos

Location Name: TEP Rocky Mountain LLC Juhan Booster Station

Location # 323868

Facility # 479766

May 13, 2024 at 12:52:45 PM



Photo # 6722 Tank label weathered & starting to become illegible.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources