


Shawnee Oil Development Inc
USA Shaw #19
Location ID: 313419



Tank labels missing required information



Tank battery sign missing required information

Shawnee Oil Development Inc
USA Shaw #19
Location ID: 313419



Debris



PVC cap leaking on tank valve

Shawnee Oil Development Inc
USA Shaw #19
Location ID: 313419



Debris



Debris

Shawnee Oil Development Inc
USA Shaw #19
Location ID: 313419



Wellhead sign missing required information



Flow line leak

Shawnee Oil Development Inc
USA Shaw #19
Location ID: 313419



Looking Northeast



Debris

Shawnee Oil Development Inc
USA Shaw #19
Location ID: 313419



Unmarked anchor



Unmarked anchor

Shawnee Oil Development Inc
USA Shaw #19
Location ID: 313419



Oil seepage downhill from wellhead. Cellar leak?



Oil seep to wellhead

Shawnee Oil Development Inc
USA Shaw #19
Location ID: 313419



Location from Northeast corner



Location from Southeast corner