

Argali Exploration Company  
McWilliams 2-31  
Location ID: 312949



Sign at separator. Incorrect phone number?



Debris



Argali Exploration Company  
McWilliams 2-31  
Location ID: 312949



**Debris**



**Wellhead fencing down. Possible wellhead leak**



Argali Exploration Company  
McWilliams 2-31  
Location ID: 312949



Horse hair on flowline



Wellhead fence down



Argali Exploration Company  
McWilliams 2-31  
Location ID: 312949



Debris




Debris

**Argali Exploration Company  
McWilliams 2-31  
Location ID: 312949**



**Debris**



**Unsatisfactory bird protection**



**Argali Exploration Company  
McWilliams 2-31  
Location ID: 312949**



**Unprotected popoff riser**



**Debris**

Argali Exploration Company  
McWilliams 2-31  
Location ID: 312949



**Unused equipment**



**Unused equipment**



**Argali Exploration Company  
McWilliams 2-31  
Location ID: 312949**



**Location from Northeast corner**



**Location from Southeast corner**



**Argali Exploration Company  
McWilliams 2-31  
Location ID: 312949**



**Location from Southwest corner**



**Location from Northwest corner**